

1303 4<sup>th</sup> Ave NE Barnesville, MN 56514 Phone: 218-789-3100

# **Board of Managers**

# Peter Fjestad

President
Otter Tail County

## Catherine Affield

Vice President Wilkin County

#### John Hanson

Secretary Becker County

#### Troy Larson

Treasurer Wilkin County

#### Gerald Van Amburg

Manager Clay County

### William Davis

Manager Clay County

## Curtis Stubstad


Manager Clay County

# **Tile Outlet Marker Policy**

Landowners are required to install and maintain tile outlet markers on all tile lines that outlet directly into public drainage systems or BRRWD projects.

#### Markers must:

- 1. be placed within 5 feet of the outlet, in line with tile, along the slope;
- 2. be a minimum of 4 feet in height;
- 3. be flexible, reflective, fiberglass posts.



The BRRWD will make every effort to avoid damage to tile lines during construction and maintenance activities. However, BRRWD is not liable for any damage caused to tile systems within their legal ditch right-of-way or project easements. Tile Outlet Marker Policy shall take effect January 1, 2024.